Selevic   No.   No.	Date:	Property is: Single Far 10/29/2015	nily		Duple	ex	☑ Other□		
take no responsibility for problems discovered after the inspection date, or for omissions through error or oversight. The list does not necessarily include work required by private lenders, insurance companies, or by the Federal Block Grant or HOME programs.  Exterior C-ordition Report  Location Site							TI 60 (140 )		
	take no respo	nsibility for problems discovered a	after th	e insp	ection d	date	, or for omissions through error or oversight. The list d		
Landscaping	Exterior (	Condition Report							
Steps/Handralls		Required Work					Note/Comments		Cost
Service walks	Site	Landscaping					Self Help Clear trees growing around parking slab	•	500.00
Fencing		Steps/Handrails	n/a	<u> </u>	Yes [			\$	
Parking		Service walks	n/a	V	Yes [			\$	
Retaining walls		Fencing	n/a	<u> </u>	Yes [			\$	
Other		Parking	n/a		Yes [	<b>√</b>		\$	2,000.00
Cither		Retaining walls	n/a	<u> </u>	Yes [			\$	
Singles: repair		Other	n/a		Yes [			\$	
Singles: repair	Garago	Other	n/a		Yes [			\$	
Shingles:Tear off & re-roof	Garage	Singles: repair	n/a		Yes [			\$	
Sutters/downspouts		Shingles: Roof over existing	n/a		Yes [			\$	
Flashing		Shingles:Tear off & re-roof	n/a		Yes [			\$	
Eaves		Gutters/downspouts	n/a		Yes [			\$	
Siding		Flashing	n/a		Yes [			\$	
Doors		Eaves	n/a		Yes [			\$	
Windows         n/a		Siding	n/a		Yes [			\$	
Slab		Doors	n/a		Yes [			\$	
Paint         n/a         Yes         \$           Electrical         n/a         Yes         \$           Other         n/a         Yes         \$           Roof         n/a         Yes         \$         900.00           Deck-upper         n/a         Yes         Replace rubber roof         \$         780.00           Deck-lower         n/a         Yes         Repair         \$         650.00           Steps/handrails         n/a         Yes         \$         \$           Ceiling         n/a         Yes         \$         \$           Guardrails         n/a         Yes         \$         \$           Structural         n/a         Yes         \$         \$           Paint         n/a         Yes         \$         \$		Windows	n/a		Yes [			\$	
Electrical		Slab	n/a		Yes [			\$	
Porches         Roof         n/a         Yes         ✓         \$ 900.00           Deck-upper         n/a         Yes         ✓ Replace rubber roof         \$ 780.00           Deck-lower         n/a         Yes         ✓ Repair         \$ 650.00           Steps/handrails         n/a         Yes         \$           Ceiling         n/a         Yes         \$           Guardrails         n/a         Yes         \$           Structural         n/a         Yes         \$           Paint         n/a         Yes         \$		Paint	n/a		Yes [			\$	
Porches         Roof         n/a         Yes         ✓         Replace rubber roof         \$ 900.00           Deck-upper         n/a         Yes         ✓         Replace rubber roof         \$ 780.00           Decklower         n/a         Yes         ✓         Repair         \$ 650.00           Steps/handrails         n/a         Yes          \$           Ceiling         n/a         Yes          \$           Guardrails         n/a         Yes          \$           Structural         n/a         Yes          \$           Paint         n/a         Yes          \$		Electrical	n/a		Yes [			\$	
Roof         n/a         Yes         ✓         Replace rubber roof         \$ 900.00           Deck-upper         n/a         Yes         ✓         Replace rubber roof         \$ 780.00           Decklower         n/a         Yes         ✓         Repair         \$ 650.00           Steps/handrails         n/a         ✓         Yes          \$           Ceiling         n/a         ✓         Yes          \$           Guardrails         n/a         ✓         Yes          \$           Structural         n/a         ✓         Yes          \$         600.00		Other	n/a		Yes [			\$	
Deck-upper         n/a         Yes         ✓ Replace rubber roof         \$ 780.00           Decklower         n/a         Yes         ✓ Repair         \$ 650.00           Steps/handrails         n/a         ✓ Yes          \$           Ceiling         n/a         ✓ Yes          \$           Guardrails         n/a         ✓ Yes          \$           Structural         n/a         ✓ Yes          \$           Paint         n/a         Yes         ✓         \$ 600.00	Porches	Roof	n/a		Yes [	য		\$	900.00
Deck-lower         n/a         Yes         ✓ Repair         \$ 650.00           Steps/handrails         n/a         ✓ Yes         \$           Ceiling         n/a         ✓ Yes         \$           Guardrails         n/a         ✓ Yes         \$           Structural         n/a         ✓ Yes         \$           Paint         n/a         Yes         ✓         \$		-					Replace rubber roof		-
Steps/handrails         n/a							=		
Ceiling       n/a ☑ Yes ☐       \$         Guardrails       n/a ☑ Yes ☐       \$         Structural       n/a ☑ Yes ☐       \$         Paint       n/a ☐ Yes ☑       \$         600.00		-						•	
Guardrails         n/a ☑ Yes □         \$           Structural         n/a ☑ Yes □         \$           Paint         n/a □ Yes ☑         \$									
Structural         n/a ☑ Yes ☐         \$           Paint         n/a ☐ Yes ☑         \$         600.00									
Paint         n/a         ☐         Yes         ☑         \$         600.00									
							-		600.00
		-					_		

Scope of Work for Property Located at: <u>2618 North 34th Street</u>

## House

Chimney	n/a ☑	Yes □		\$ 
Shingles: repair	n/a ☑	Yes 🗆		\$ 
Shingles: Roof over existing	n/a ☑	Yes 🗆		\$ 
Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 9,000.00
Gutters/downspouts	n/a □	Yes ☑		\$ 1,000.00
Flashing	n/a ☑	Yes 🗆		\$ 
Eaves	n/a ☑	Yes □		\$ 
Siding	n/a ☑	Yes 🗆		\$ 
Storm Doors	n/a ☑	Yes □		\$ 
Prime ("main") Doors	n/a □	Yes ☑		\$ 700.00
Storm Windows	n/a □	Yes ☑		\$ 200.00
Prime ("main") Windows	n/a □	Yes ☑		\$ 700.00
Paint	n/a 🔲	Yes ☑	Previously painted surfaces	\$ 1,420.00
Foundation	n/a ☑	Yes 🗆		\$ 
Electrical	n/a ☑	Yes □	-	\$ 
Other	n/a □	Yes ☑	Address Numbers - alley side	\$ 25.00
Other	n/a □	Yes ☑	Second floor NE bedroom requires ventilation and	\$ 800.00
Other	n/2 🔽	Yes □	lighting per code	\$ 
	n/a □			
Other	n/a □	Yes □		\$ 

Exterior: Estimated Cost:\* \$
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

19,275.00

interior Co	onaition Report								
	Unit: Entire unit (single family)	_				Lower unit of duplex	<b>V</b>		
Mechanical	Upper unit of duplex Required Work					Other			
Heating									
	Repair/replace boiler	n/a	V	Yes		_		 \$	
	Repair radiation	n/a	V	Yes				 \$	
	Repair/replace furnace	n/a	<b>✓</b>	Yes		_		 \$	
	Repair ductwork	n/a		Yes	<b>V</b>	<u> </u>		 \$	300.00
	Replace thermostat	n/a		Yes	<b>V</b>			\$	100.00
	Repair/replace grilles	n/a		Yes	<b>V</b>	_		\$	300.00
et	Tune boiler/furn. insp ht exchang	j€n/a		Yes	V			\$	350.00
Electrical	Repair/replace receptacles	n/a		Yes	<b>V</b>			\$	500.00
	Repair/replace switches	n/a		Yes	<b>V</b>			\$	500.00
	Repair/replace fixtures	n/a		Yes	<b>V</b>			\$	500.00
	Install outlets and circuits	n/a	<b>V</b>	Yes				\$	
	Install outlets and circuits	n/a	<b>V</b>	Yes				 \$	
	Install outlets and circuits	n/a	<b>V</b>	Yes				\$	
	Install outlets and circuits	n/a	<b>V</b>	Yes				 \$	
	Upgrade service	n/a	<b>V</b>	Yes				\$	
	Other	n/a		Yes				\$	
<b>.</b>	Other	n/a		Yes		_		 \$	
Plumbing	Repair/replace kitchen sink	n/a	<b>V</b>	Yes				\$	
	Repair/replace kitchen sink fauce	ein/a	<b>V</b>	Yes				 \$	
	Repair/replace tub	n/a	<b>V</b>	Yes				\$	
	Repair/replace tub faucet	n/a		Yes	V			\$	400.00
	Repair/replace toilet	n/a	<b>V</b>	Yes				\$	
	Repair/replace lavatory	n/a	<b>V</b>	Yes				 \$	
	Repair/replace lavatory faucet	n/a	<b>V</b>	Yes				 \$	
	Repair/replace wash tub	n/a	<b>V</b>	Yes				\$	
	Repair/replace wash tub faucet	n/a	<b>V</b>	Yes				\$	
	Unclog piping:	n/a	<b>V</b>	Yes				 \$	
	Repair drain/waste/vent piping	n/a		Yes	<b>V</b>			 \$	220.00
	Repair water piping	n/a	<b>V</b>	Yes				\$	
	Repair/replace water heater	n/a		Yes	V	Service		\$	300.00
	Other	n/a	V	Yes				\$	
	Other	n/a		Yes				\$	

	Replace broken glass	n/a ☑	Yes □		\$	
	Repair or replace sash	n/a ☑	Yes 🗆		\$	
Doors	Repair or replace doors	n/a □	Yes 🗸		\$	380.00
	Repair or repl. locks/latches	n/a □	Yes ✓	Self Help	\$	110.00
Walls/Ceilin	Repair or repl. @ defective	n/a □	Yes ☑		\$	1,600.00
Paint	Repair or repl. @ defective	n/a □	Yes ☑		\$	800.00
Fire Safety					*	
o Galoty	Install smoke/CO alarm:bsmt.	n/a □	Yes ✓	Self Help	\$	55.00
	Install smoke/CO alarm: 1st flr.	n/a □	Yes ✓	Self Help	\$	165.00
	Install smoke/CO alarm: 2nd flr.	n/a ☑	Yes 🗆	Self Help	\$	
Handrails	Repair/replace defective	n/a 🔽	Yes □	Self Help	\$	
Stairs	Repair defective	n/a ☑	Yes □		\$	
Floors	Repair defective	n/a □	Yes 🔽		\$	900.00
Other		n/a □	Yes 🗆		\$	
	-				·	
		n/a □	Yes 🗆	_	\$	
		n/a □	Yes 🗆	_	\$	
		n/a □	Yes □		\$	

Interior Co	ondition Report								
Machanical	Unit: Entire unit (single family) Upper unit of duplex Required Work	□				Lower unit of duplex Other			
Heating	nequired work								
	Repair/replace boiler	n/a	<b>V</b>	Yes		_		\$ 	
	Repair radiation	n/a	<b>V</b>	Yes				\$ 	
	Repair/replace furnace	n/a	V	Yes				\$ 	
	Repair ductwork	n/a		Yes	✓	_		\$ 300.	00
	Replace thermostat	n/a		Yes	<b>V</b>			\$ 100.	00
	Repair/replace grilles	n/a		Yes	<b>V</b>			\$ 300.	00
Electrical	Tune boiler/furn. insp ht exchang	€n/a		Yes	V			\$ 350.	00
Liectificai	Repair/replace receptacles	n/a		Yes	V			\$ 500.	00
	Repair/replace switches	n/a		Yes	<b>√</b>			\$ 500.	00
	Repair/replace fixtures	n/a		Yes	<b>V</b>			\$ 500.	00
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$ 	
	Install outlets and circuits	n/a	V	Yes				\$ 	
	Install outlets and circuits	n/a	V	Yes				\$	
	Upgrade service	n/a	V	Yes				\$	
	Other	n/a		Yes				\$ 	
Di	Other	n/a		Yes				\$ 	
Plumbing	Repair/replace kitchen sink	n/a	V	Yes				\$ 	
	Repair/replace kitchen sink fauce	ein/a	V	Yes				\$	
	Repair/replace tub surround	n/a		Yes	<b>V</b>	Install tub and showe	r surround	\$ 500.	00
	Repair/replace tub faucet	n/a		Yes	V			\$ 400.	00
	Repair/replace toilet	n/a	V	Yes				\$ 	
	Repair/replace lavatory	n/a	V	Yes				\$	
	Repair/replace lavatory faucet	n/a	<b>V</b>	Yes				\$ 	
	Repair/replace wash tub	n/a	V	Yes				\$ 	
	Repair/replace wash tub faucet	n/a	V	Yes				\$	
	Unclog piping:	n/a	<b>V</b>	Yes		-		\$ 	
	Repair drain/waste/vent piping	n/a		Yes	V			\$ 440.	00
	Repair water piping	n/a	V	Yes				\$ 	
	Repair/replace water heater	n/a	<b>V</b>	Yes	<b>V</b>			\$ 800.	00
	Other	n/a		Yes	<b>V</b>	Replace gas line to w	ater heater	\$ 250.	00

n/a 

Yes 

Remove old laundry tub and terminate drain

250.00

Other

Windows						
	Replace broken glass	n/a ☑	Yes		\$	
Doors	Repair or replace sash	n/a ☑	Yes 🗆		\$	
Doors	Repair or replace doors	n/a □	Yes 🗸		\$	380.00
	Repair or repl. locks/latches	n/a □	Yes ✓	Self Help	\$	110.00
Walls/Ceiling	gs Repair or repl. @ defective	n/a □	Yes ☑		\$	600.00
Paint	Repair or repl. @ defective	n/a □	Yes ☑		\$	500.00
Fire Safety	<u> </u>				*	
i lie Salety	Install smoke/CO alarm:bsmt.	n/a ☑	Yes 🗆	Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a □	Yes ☑	Self Help	\$	165.00
	Install smoke/CO alarm: 2nd flr.	n/a ☑	Yes □	Self Help	\$	
Handrails	Repair/replace defective	n/a ☑	Yes □	Self Help	\$	
Stairs	Repair defective	n/a ☑	Yes □		\$	
Floors	Repair defective	n/a □	Yes 🔽		\$	1,200.00
Other	поран астестіче	πα 📋	103 V		Ψ	1,200.00
		n/a □	Yes ☑	Guard rail and hand rail in attic	\$	750.00
		n/a □	Yes 🗆		\$	
		n/a □	Yes □		\$	
		n/a □	Yes 🗆		\$	
				Interior: Estimated Cost:	\$	16,375.00
				Total Exterior and Interior Cost:*	\$	35,650.00

Inspected by: Jeremy Belot Date: 10/29/2015

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 West Mill Road.

 $<sup>^{\</sup>star}$ average contracted cost. Actual costs may vary. Self help will reduce the amount.